

STATE OF NEW MEXICO 1096
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT TO THE PARTMENT OF THE PARTMENT OF

MINING AND MINERALS DIVISION
2040 SOUTH PACHECO

SANTA FE, NEW MEXICO 87505 TELEPHONE: (505) 827-5970

FAX: (505) 827-7195

# MINING ACT RECLAMATION BUREAU ANNUAL REPORT OF MINING OPERATIONS

The permittee shall submit a report for the preceding calendar year on or before April 30th of each calendar year after a permit has been issued. Name of Company/Applicant: QUIVIRA MINING COMPANY Permit Number: MK002RE Name and Title of Responsible Official: TERRY L. FLETCHER, **GENERAL MANAGER** P.O. BOX 218, GRANTS, NM 87020 Project Name: SECTION 35 MINE Status of Operation: Check (✓) one of the following: 

Active Existing; 

Active New; Inactive Existing; 

Inactive New Underground; ☐ Open Pit; ☐ Insitu Leach/Heap Leach; ☐ Mill; Type of Operation: ☐ Other (please describe): Production information: URANIUM Type(s) of Commodity produced: Annual Production: (to be held as confidential) Please provide this information on the Mining Registration, Reporting and Safeguarding Program form recently sent to all operators. Do not report production data on this form. Disturbance and Reclamation: Total Disturbed Acres: Acres Disturbed during the Report Year: \_\_\_ В. Total Acres Reclaimed during the Report Year: Total Acres Reclaimed to Date: 10.7 C. D. 29.3 E. Total Disturbed Acres not yet Reclaimed: F. On separate maps, identify the location of the disturbed areas and areas of reclaimed land along with the year in which the work was done. Ore storage pad was stabilized with an average of one foot of alluvium an revegetated. Financial Assurance: Indicate the current market value of any collateral posted: (\$)

#### Compliance Status:

Indicate compliance status for all existing State and federal environmental permits held by the permittee for this operation:

Permit No.	Permit Name	Issuing	Agency	Status	<b>Expiration Date</b>
MK002RE	MINE PERMIT	•	MMD	COMPLIANCE	N/A
DP-67	DISCHARGE I	PLAN	NMED	COMPLIANCE	8/19/95*
NMR00A192	STORM WA	ATER	EPA	COMPLIANCE	10/1/97

\* - Timely renewal for discharge plan DP-67 requested on April 11, 1995; awaiting NMED approval.

I hereby affirm that the information provided is true, complete and correct:

Signature

4/29/9C Date

TERRY L. FLETCHER, GENERAL MANAGER

Please Print Name and Title

The submittal of this 1995 Annual Report by Quivira Mining Company does not alter Quivira's contention as presented during the May 12, 1994 New Mexico Mining Commission hearings, that uranium mines may not be subject to the New Mexico Mining Act pursuant to the definition of "Mineral" and/or "Mining" because uranium is a commodity, byproduct material or waste that is regulated by the Nuclear Regulatory Commission (NRC) and/or involves the extraction, processing or disposal of same or of activities regulated by NRC; and also because of the extensive federal and state duplicative regulations and preemption of regulatory power over uranium and over the above listed activities. With this submittal, Quivira does not waive or prejudice its position that its operations may be excluded from the applicability of the Act.

## QUIVIRA MINING COMPANY SECTION 35 MINE Permit MK002RE

### Annual Report Map

The attached map is submitted pursuant to Rule 509.C of the New Mexico Mining Act Regulations. This map supplements the *Annual Report of Mining Operations*.

## 1995 Summary

The Section 35 mine remained on deferred production status during the calendar year 1995.

## **Reclamation Summary**

No reclamation activity occurred at the Section 35 mine during calendar year 1995. However, pursuant to the Mining Act Regulations and mining permit issued for the Section 35 mine, Quivira Mining Company submitted a closeout plan for the mine on December 29, 1995.

Past reclamation activities included:

1993: Sta

Stabilizing the ore storage pad with an average of one foot of

alluvium;

1994:

Revegetation activities on the ore storage pad.

